

Effective SAFETY Solutions

WHERE

Company: Assan Demir ve Saç Sanayi A.S.

Location: Istanbul, Turkey

Business: Aluminium sheet and foil products

Contact person: Hakan Özer , HSE Manager

THE ISSUE

Aluminium coils rolled down the pedestrian area

THE SOLUTION (additional level of protection put in place)

Type: (Technical - Procedures - Others)

Description of key feature or change versus current conditions:

To prevent coils rolling down we made the steel shelves to store the coils. Also we put steel bars both end of the coil storage lines

PICTURES or ADDITIONAL INFO



Figure.1 & 2 Stored coils jumped over the palette and fell on the pedestrian area.



Figure.3 Steel bars were mounted both end of the Storage lines of the coils.



Figure 4. New coil storage shelves were made.

Effective SAFETY Solutions

SAFETY BENEFITS – pros/cons

- To prevent workers from any unexpected the accident may occur in the future
- To prevent materials from any damage may occur in the future

IMPLEMENTATION COST (k€) AS APPLICABLE
